



| Numer artykułu | Symbol | Wymiary, mm |   |    |    |     | Ilość otworów<br>∅ 4,5 |
|----------------|--------|-------------|---|----|----|-----|------------------------|
|                |        | A = B = C   | D | E  | F  | G   |                        |
| 401100         | KS 1   | 30          | 2 | 8  | 13 | 7,5 | 4                      |
| 401200         | KS 2   | 40          | 2 | 10 | 15 | 10  | 4                      |
| 401300         | KS 3   | 60          | 2 | -  | 25 | 10  | 8                      |
| 401120         | KSC 1  | 30          | 2 | 8  | 13 | 7,5 | 4                      |
| 401220         | KSC 2  | 40          | 2 | 10 | 15 | 10  | 4                      |
| 401320         | KSC 3  | 60          | 2 | -  | 25 | 10  | 8                      |

**Rys. 19.** Łączniki odporowe kątowe (płaskie) KS